


Fuel Nozzle



Section	Accessories
ATA chapter	73-10-05 , 73-11-08
Check & Test Total Time	14 (days)
Overhaul Total Time	21 (days)
Quantity (min)	10 Each

PW 100 & 200

Part Numbers

3034205	3034208	3035057	3037385	3038099	3038109	3038705	3039719	3039745	3040144
3034215	3034731	3037380	3037422	3038103	3038117	3038706	3039720	3039746	3040145
3034219	3034733	3037381	3037423	3038104	3038118	3038707	3039741	3039971	3040146
3034222	3035048	3037382	3037425	3038105	3038699	3038825	3039742	3039975	3043978-01
3034225	3035049	3037383	3037426	3038106	3038703	3038826	3039743	3040142	3043979-01
3034729	3035056	3037384	3038098	3038108	3038704	3038827	3039744	3040143	3043980-01
3053909-01	3053915-01	3056565-03	01R3053906-01	3079014-01	3039265	3053895-01	3045776-01	3045667	3043981-01
02R3053909-01	02R3053915-01	02R3049749-01	02R3053906-01	3039260	3076569-01	02R3053895-01	3045778-01	3045668	01R3043981-01
03R3053909-01	03R3053915-01	3049750-01	3053907-01	3076572-01	3039409	03R3053895-01	3045781-01	3045669	02R3043981-01
3053910-01	3053916-01	01R3049750-01	02R3053908-01	3039707	3044180-01	3053903-01	3045783-01	3045670	3043982-01
01R3053910-01	02R3053916-01	02R3049750-01	03R3053908-01	3044285-01	3055353-02	01R3053903-01	3045786-01	3045672	01R3043982-01
02R3053910-01	03R3053916-01	02R3053907-01	3056042-02	3056042-01	3055353-03	02R3053903-01	3045788-01	3045673	02R3043982-01
3053912-01	3053917-01	03R3053907-01	3122709-02	3039264	3056565-01	3079012-01	3049418-01	3045692	3045307
02R3053912-01	02R3053917-01	3053908-01	3039410	3049749-01	3056565-02	3079013-01	3053906-01	01R3049749-01	02R3045669
03R3053912-01	03R3053917-01	02R3053914-01	01R3053914-01	3053914-01	02R3053913-01	3059760-01	3059757-01	3059754-01	01R3049418-01
3053913-01	3053918-01	02R3053918-01	01R3053918-01	01R3053913-01	02R3049748-01	01R3049748-01	3049748-01	02R3049418-01	

Repair Code	Repair No.	Repair Description	Price per Each
10		CHECK & TEST	
	C1	Incoming Reveal Acceptance Visual Check to Detect the Defects External Cleaning Check (Include Visual Inspection, Dimensional Inspection, FPI) Performing Functional Test Issue of Certificate Preservation & Vacuum Packing.	
20		OVERHAUL	
	-	Incoming Reveal Acceptance	
	-	Disassembly	
	-	Ultrasonic Cleaning	
	-	Check (Include Visual Inspection, Dimensional Inspection, FPI)	
	01	Crack Repair of the Sheath	
	02	Surface Restoration of the Adapter (Adapter body and Sheath)	
	03	Repair of Axial Scratches (ID of Inlet ports and Drain)	

04	Surface Restoration of the Fuel Nozzle Body
05	Restoration of the sealing Surface
06	Repair of the Strainer Sleeve Grooves
07	Repair of the Adapter Threads
08	Repair of the Adapter Threads
09	Replacement of the Straight Headless Pin
10	Surface Repair of the Aircap, the Lockring and the Sleeve
11	Correction of Narrow Spray Angle
12	Correction of Narrow Spray Angle
13	Correction of Wide Spray Angle
14	Correction of Streaks and Voids
15	Correction of Streaks and Voids
16	Correction of High Flow
17	Repair of the Fuel Nozzle Threads
18	Crack Repair at Crimp Area
19	Surface Restoration of the Exit Face
20	Surface Restoration of the Plate
21	Replacement of the Lockring
22	Surface Restoration of the Plug and/or Correction of High Flow
23	Replacement of the Sleeve
-	Missing Parts Replacement*
-	Assembly
-	Performing Functional Test
-	Issue of Certificate
-	Preservation & Vacuum Packing.

NOTE1: Material Replacement

Replacement with new material will be charged according OEM current list price plus a handling charge of 15%.

NOTE2: *If Required