

Thermocouple Harness EGT



Section	Accessories
ATA chapter	72-00-17
Check & Test Total Time	7 (days)
Repair Total Time	20 (days)
Quantity (min)	1 Each

LF507-1F Engine

Part Numbers

2-310-078-01

Repair Code	Repair No.	Repair Description	Price per Each
10		CHECK & TEST	
	C1	Incoming Receiving Acceptance Visual Check to Detect the Defects External Cleaning Check (Include Visual Inspection, Dimensional Inspection) Performing Functional Test Issue of Certificate Vacuum Packing.	
20		Repair	
	**	Incoming Receiving Acceptance External Cleaning Check (Include Visual Inspection, Dimensional Inspection) Repair Damaged Probes Missing Parts Replacement* Performing Functional Test Issue of Certificate Vacuum Packing.	

NOTE1: Material Replacement

Replacement with new material will be charged according OEM current list price plus a handling charge of 15%.

NOTE2: *If Required

NOTE3: **IAW SHP-SB-002 (03 Mar.2021)