

Fuel Nozzle



Section	Accessories
ATA chapter	73-11-06
Check & Test Total Time	14 (days)
Overhaul Total Time	21 (days)
Quantity (min)	10 Each

Tay650

Part Numbers

6830096E8 6830096E9 6830096E10 6830096E8ZA 6830096E9ZA 6830096E10ZA 6830096E19 6830096E20 6830096E21 6830096E27

Repair Code	Repair No.	Repair Description	Price per Each
10		CHECK & TEST	
	C1	Incoming Receival Acceptance Visual Check to Detect the Defects External Cleaning Check (Include Visual Inspection, Dimential Inspection) Performing Functional Test Issue of Certificate Preservation & Vacuum Packing.	
20		OVERHAUL	
		Incoming Receival Acceptance Disassembly Ultrasonic Cleaning Visual Check	
	01	Repair Damaged Threads*	
	02	Repair Damaged Seal Surfaces*	
	03	Repair Damaged Locating Sleeve (Replacement) *	
	04	Removal Of Burrs or Rased Metal*	
	05	Polish Swirler Assembly* Missing Parts Replacement* Assembly Performing Functional Test Issue of Certificate Preservation & Vacuum Packing.	

NOTE1: Material Replacement

Replacement with new material will be charged according OEM current list price plus a handling charge of 15%.

NOTE2: *If Required