

## Fuel Nozzle



Section	Accessories
ATA chapter	73-15-01
Check & Test Total Time	14 (days)
Overhaul Total Time	21 (days)
Quantity (min)	10 Each

## LF-Manifold

### Part Numbers

Delevan:37112  
Honeywell:2-300-677-04

Delevan:46795  
Honeywell:2-300-677-06

Delevan:48207  
Honeywell:2-310-011-01

Delevan:56520  
Honeywell:2-310-071-01

Delevan:59117  
Honeywell:2-310-098-01

Delevan:152805  
Honeywell:2-310-213-01

Repair Code	Repair No.	Repair Description	Price per Each
10		<b>CHECK &amp; TEST</b>	
	CI	Incoming Receiving Acceptance Visual Check to Detect the Defects External Cleaning Check (Include Visual Inspection, Dimensional Inspection, FPI) Performing Functional Test Issue of Certificate Preservation & Vacuum Packing.	
20		<b>OVERHAUL</b>	
	-	Incoming Receiving Acceptance	
	-	Disassembly	
	-	Ultrasonic Cleaning	
	-	Check (Include Visual Inspection, Dimensional Inspection, FPI)	
	01	Repair of Primary and Secondary seal surfaces	
	02	Primary Seal Surface to Flange Dimensional Requirements	
	03	Correct undersize dimension	
	04	Damage on Air Cap	
	05	Machining Dimensions for Removal of Air Cap	
	06	Repair damage to threads	
	07	Correct high primary flow rate	
	08	Polishing of Exit Orifice	
	09	Down Calibration of Secondary	
	10	Correct low secondary flow rate	
	-	Missing Parts Replacement*	
	-	Assembly	
	-	Performing Functional Test	
	-	Issue of Certificate	
	-	Preservation & Vacuum Packing.	

NOTE1: Material Replacement

Replacement with new material will be charged according OEM current list price plus a handling charge of 15%.

NOTE2: \*If Required