


Fuel Control Assy.



Section	Accessories
ATA chapter	49-31-61 , 49-31-65
Check & Test Total Time	10 (days)
Repair Total Time	20 (days)
Quantity (min)	1 Each

GTCP 331 Family APU

Part Numbers

3882500-6	3882500-14	3883240-3	3882500-10
3882500-7	3882500-15	3883240-5	3882500-11
3882500-8	3882500-16	3883240-6	3882500-12
3882500-9	3882500-17	3883240-7	3882500-13

Repair Code	Repair No.	Repair Description	Price per Each
10		CHECK & TEST	
	Cl	Incoming Reival Acceptance Visual Check to Detect the Defects External Cleaning Check (Include Visual Inspection, Dimential Inspection) Performing Functional Test Issue of Certificate Preservation & Vacuum Packing.	
20		Repair	
	-	Incoming Reival Acceptance	
	-	Disassembly	
	-	Ultrasonic Cleaning	
	-	Check (Include Visual Inspection, Dimential Inspection)	
	01	FUEL CONTROL HOUSING REPAIR	
	02	TORQUE MOTOR REPAIR	
	03	FILTER BODY REPAIR	
	04	CARRIER ASSEMBLY REPAIR	
	05	DRIVE GEARSHAFT REPAIR	
	-	Missing Parts Replacement*	
	-	Assembly	
	-	Performing Functional Test	
	-	Issue of Certificate	
	-	Preservation & Vacuum Packing.	

NOTE1: Material Replacement

Replacement with new material will be charged according OEM current list price plus a handling charge of 15%.

NOTE2: *If Required