

Lead Thermocouple Assembly



Section	Accessories
ATA chapter	72-00-16
Check & Test Total Time	5 (days)
Quantity (min)	1Each

LF507-1F Engine

Part Numbers

2-310-089-01	2-310-089-02
--------------	--------------

Repair Code	Repair No.	Repair Description	Price per Each
10		CHECK & TEST	
	Cl	Incoming Receiving Acceptance Visual Check to Detect the Defects External Cleaning Check (Include Visual Inspection, Dimensional Inspection) Performing Functional Test Issue of Certificate Vacuum Packing.	

NOTE1: Material Replacement

Replacement with new material will be charged according OEM current list price plus a handling charge of 15%.

NOTE2: *If Required